

▼

DEPARTURE ROUTE DESCRIPTION

TAKEOFF RUNWAY 13: Climb on heading 129° to 1800 before turning westbound or as assigned by ATC, thence. . .

TAKEOFF RUNWAY 17: Climb on heading 174° to 2600 before turning westbound or as assigned by ATC, thence. . .

TAKEOFF RUNWAY 31: Climb on heading 309° to 1500 before turning southbound or as assigned by ATC, thence. . .

TAKEOFF RUNWAY 35: Climb on heading 354° to 1400 before turning southbound or as assigned by ATC, thence. . .

. . .expect RADAR vectors to cross CUZNO at or above 3000, then on track 357° to cross NANDR at or below 13000, then on assigned transition.

EAKER TRANSITION (NANDR3.EAKER)

MC ALESTER TRANSITION (NANDR3.MLC)

OKMULGEE TRANSITION (NANDR3.OKM)

ROLLS TRANSITION (NANDR3.ROLLS)

TULSA TRANSITION (NANDR3.TUL)

WILL ROGERS TRANSITION (NANDR3.IRW)

ZEMMA TRANSITION (NANDR3.ZEMMA)