

VOR/DME or TACAN RWY 34L  
JACKSON-MEDGAR WILEY EVERS INTL (JAN)

**MISSED APPROACH:** Climbing right turn to 3000 on heading 120° and MHZ VORTAC R-134 to RAKIN INT/ MHZ 16.5 DME and hold.

TDZL/RCLS Rwy's 16L and 34L  
 REIL Rwy's 16R and 34R  
 HIRL Rwy's 16L-34R and 16R-34L

Figure 1: Sample chart showing a track with a change of heading. The track starts at a heading of 120° and changes to 172°. The distance between the change of heading and the next fix is 3.6 NM. The track is labeled with 'CAYAD MHZ 13.5' and '2100'. The track is also labeled with 'MHZ 8.5' and 'MHZ 9.9'. The track is labeled with '3.05° TCH 55'.