

PALMER**ABI** (AK46) PVT 2 N UTC-9(-8DT) N61°37.73' W149°02.59'

ANCHORAGE

750 NOTAM FILE Not insp.

RWY 07-25: 1000X40 (GRVL)**RWY 25:** P-line.**AIRPORT REMARKS:** Attended continuously. Rwy 25 has a road that crosses AER 730' from thld.**AIRPORT MANAGER:** 907-745-3124**COMMUNICATIONS:** CTAF 123.6**COMM/NAV/WEATHER REMARKS:** For a local call to Palmer FSS dial 745-2495. For a toll free call to Kenai FSS dial 1-866-864-1737.**BUTTE MUNI** (AK1) 5 SE UTC-9(-8DT) N61°31.82' W149°01.06'

ANCHORAGE

64 NOTAM FILE ENA

RWY 07-25: 1806X50 (GRVL-DIRT)**RWY 07:** Trees.**RWY 25:** Tree.**AIRPORT REMARKS:** Unattended. Road alg N and S side of rwy. Rwy 07-25 safety area clr 1800' X 200'. Rwy 07 end, 400' safety area. Rwy 07-25 dips and 3" rocks. Nstd windsock, yellow, unrelbl. Rwy cond unmnt, visual inspn recmdd bfr lndg.**AIRPORT MANAGER:** 907-745-4557**COMMUNICATIONS:** CTAF 123.6**RADIO AIDS TO NAVIGATION:** NOTAM FILE ENA.**BIG LAKE (H) (H) VORTACW** 112.5 BGQ Chan 72 N61°34.17' W149°58.03' 076° 27.4 NM to fld. 179/19E.TACAN AZIMUTH unusable:
230°-245° byd 38 blo 8,000'DME unusable:
230°-245° byd 38 blo 8,000'**COMM/NAV/WEATHER REMARKS:** For a local call to Palmer FSS dial 745-2495. For a toll free call to Kenai FSS dial 1-866-864-1737.