

CALDWELL**NOBLE CO** (I10) 3 N UTC-5(-4DT) N39°48.06' W81°32.18'**CINCINNATI**

879 B NOTAM FILE CLE

L-29B**RWY 05-23:** H3811X65 (ASPH) S-12.5 MIRL**IAP****RWY 05:** Trees.**RWY 23:** PAPI(P2L)—GA 3.5° TCH 63'. Thld dsplcd 413'. Trees.**SERVICE:** LGT ACTIVATE ABn—122.7. ACTIVATE MIRL Rwy 05-23—122.7. PAPI Rwy 23 opr consly.**AIRPORT REMARKS:** Unattended. Deer birds and otr wildlife on and invof arpt. Rwy 23 red obstruction lgts mark 56' hill/terrain 1130' fm thr.**AIRPORT MANAGER:** 740-581-0557**COMMUNICATIONS:** CTAF/UNICOM 122.8® **INDIANAPOLIS CENTER APP/DEP CON** 124.45**CLEARANCE DELIVERY PHONE:** For CD ctc Cleveland ARTCC at 440-774-0226/0490.**RADIO AIDS TO NAVIGATION:** NOTAM FILE ZZV.**ZANESVILLE (DH) DME** 114.95 ZZW Chan 96(Y) N39°56.45' W81°53.56' 117° 18.5 NM to fld. 898.

DME unusable:

160°-170° byd 30 NM blo 3,500'

CAMBRIDGE MUNI (CDI)(KCDI) 3 S UTC-5(-4DT) N39°58.50' W81°34.66'**CINCINNATI**

799 B NOTAM FILE CDI

L-29B**RWY 04-22:** H4298X75 (ASPH-GRVD) S-24 MIRL**IAP****RWY 04:** REIL. PAPI(P4L)—GA 4.0° TCH 29'. Thld dsplcd 400'. P-line.**RWY 22:** REIL. PAPI(P4R)—GA 3.55° TCH 28'. Road.**SERVICE:** FUEL 100LL, JET A+ LGT ACTIVATE REIL Rwy 04 & 22; MIRL Rwy 04-22—CTAF. PAPI Rwy 04 & 22 opr consly. PAPI Rwy 04 unusbl byd 4° left and 8° right and of cntrln. PAPI Rwy 22 unusbl byd 8° left and 4° right of cntrln.**AIRPORT REMARKS:** Attended Mon-Sat 1300-2200Z. Deer, birds & otr wildlife invof arpt. 100LL avbl H24 self svc via credit card; full svc avbl when atndd. Jet A avbl full svc only. For svc aft hrs call amgr. Ramp fees for coml acft, exc flt trng acft, CDI based acft, ovngt hngr stay, fuel purchase of 25 gallons or top off. Tsnt hngr PPR.**AIRPORT MANAGER:** 740-260-7558**WEATHER DATA SOURCES:** AWOS-3 118.525 (740) 435-0086.**COMMUNICATIONS:** CTAF/UNICOM 123.075® **INDIANAPOLIS CENTER APP/DEP CON** 124.45 (West Side Opns)® **CLEVELAND CENTER APP/DEP CON** 126.95 (East Side Opns) ctc Cleveland ARTCC at 440-774-0226.**CLEARANCE DELIVERY PHONE:** For CD ctc Cleveland ARTCC at 440-774-0226/0490.**RADIO AIDS TO NAVIGATION:** NOTAM FILE ZZV.**ZANESVILLE (DH) DME** 114.95 ZZW Chan 96(Y) N39°56.45' W81°53.56' 082° 14.7 NM to fld. 898.

DME unusable:

160°-170° byd 30 NM blo 3,500'

NEWCOMERTOWN (L) DME 111.8 CTW Chan 55 N40°13.75' W81°28.59' 197° 15.9 NM to fld.

1180. NOTAM FILE CLE.

DME unusable:

010°-074° byd 28 NM blo 4,000'

075°-085° byd 23 NM blo 7,100'

086°-140° byd 28 NM blo 4,000'

CANTON**STARK CO SHERIFF HELIPORT** (5D1) 4 E UTC-5(-4DT) N40°50.41' W81°18.50'**DETROIT**

1135 NOTAM FILE CLE

HELIPAD H1: H120X75 (ASPH)**HELIPAD H1:** Pole.**HELIPORT REMARKS:** Attended continuously. Ingress/Egress clwks fm pad. Ingress NE FATO 220° +/-10°, egress NE FATO 040° +/-10°. Rcndd apch hdg 210°-230°; dep hdg 030°-050°.**AIRPORT MANAGER:** 234-804-1440**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Cleveland Apch at 216-352-2323, when Apch clsd ctc Cleveland ARTCC at 440-774-0223/0490.**CARROLL CO/TOLSON** (See CARROLLTON on page 269)