

BURNETT CO (See SIREN on page 391)**CABLE UNION** (3CU) 2 SE UTC-6(-5DT) N46°11.70' W91°14.91'**GREEN BAY**

1360 B NOTAM FILE GRB

L-141

RWY 17-35: H3709X75 (ASPH) S-28 MIRL 0.4% up S

IAP

RWY 17: Thld dsplcd 191'. Trees.**RWY 35:** Thld dsplcd 563'. Trees.**RWY 08-26:** 2194X150 (TURF)**RWY 08:** Thld dsplcd 378'. Trees.**RUNWAY DECLARED DISTANCE INFORMATION****RWY 17:** TORA-3709 TODA-3709 ASDA-3709 LDA-3519**RWY 35:** TORA-3709 TODA-3709 ASDA-3709 LDA-3146**SERVICE:** FUEL 100LL LGT MIRL Rwy 17-35 present to low SS-SR; to incr intst and actvt—CTAF.**AIRPORT REMARKS:** Unattended. Fgt wildlife on & invof arpt. 100LL: 24 hr self svc fuel avbl with credit card. Rwy 08-26

CLOSED Nov 21-May 1. Rwy 08-26 mkd with yellow cones. Rwy conditions not reported. Plug in avbl. No heating units avbl to start acft. Twy lgts at entrance to twy only.

AIRPORT MANAGER: 715-798-3240**COMMUNICATIONS:** CTAF/UNICOM 122.8**② MINNEAPOLIS CENTER APP/DEP CON** 126.45**CLEARANCE DELIVERY PHONE:** For CD ctc Minneapolis ARTCC at 651-463-5588.**RADIO AIDS TO NAVIGATION:** NOTAM FILE HYR.**HAYWARD (L) DME** 113.4 HYR Chan 81 N46°01.14' W91°26.78' 038° 13.4 NM to fld. 1208.

DME unusable:

Blw 10,000'

Byd 20 NM

CAMP LAKE (49C) 1 W UTC-6(-5DT) N42°31.67' W88°09.37'**CHICAGO**

749 TPA—1349(600) NOTAM FILE GRB

RWY 18-36: 2210X75 (TURF)**RWY 18:** Bldg.**RWY 36:** Trees.**SERVICE:** S4**AIRPORT REMARKS:** Unattended. Deer and birds on and invof arpt. Arpt not plwd; cfm conds with amgr. Rwy 18-36 mkd with orange/white A-frames**AIRPORT MANAGER:** 847-612-8552**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Chicago ARTCC at 630-906-8921.**CAPITOL DRIVE** (See BROOKFIELD on page 343)**CARTER** (See PULASKI on page 384)**CASSVILLE MUNI** (C74) 1 SE UTC-6(-5DT) N42°42.26' W90°57.97'**CHICAGO**

627 NOTAM FILE GRB

L-28G

RWY 11-29: H3000X50 (ASPH) S-21, D-40 RWY LGTS(NSTD)**RWY 11:** Fence. Rgt tfc.**RWY 29:** Thld dsplcd 600'. Road.**SERVICE:** LGT Thld lgts emit green only.**AIRPORT REMARKS:** Unattended. For winter conditions and snow removal call arpt manager. Rwy 11-29 has numerous cracks and vegetation growing entire pavement length. 1350 ft x 20 ft inline twy west of Rwy 11. 270' bluff parallels rwy 800' north.**AIRPORT MANAGER:** 608-732-8727**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Chicago ARTCC at 630-906-8921.**RADIO AIDS TO NAVIGATION:** NOTAM FILE DBQ.**DUBUQUE (VH) (H) VORTACW** 115.8 DBQ Chan 105 N42°24.09' W90°42.54' 324° 21.4 NM to fld. 1051/4E.

TACAN AZIMUTH unusable:

119°-129° byd 28 NM blo 3,100'

170°-265° blo 17,500'

DME unusable:

171°-199°

VOR unusable:

021°-028° byd 40 NM

064°-073° byd 40 NM

107°-117° byd 40 NM

199°-218° byd 40 NM

325°-335° byd 40 NM