

WINDSOR LOCKS**BRADLEY INTL** (BDL)(KBDL) P (ANG ARNG) 3 W UTC-5(-4DT) N41°56.34'**NEW YORK**

W72°41.06'

H-10I, 11D, 12K, L-33C, 34I

173 B TPA—See Remarks LRA Class I, ARFF Index C NOTAM FILE BDL MON Airport

IAP, AD**RWY 06-24:** H9510X200 (ASPH-GRVD) S-200, D-200, 2S-175, 2D-350, 2D/2D2-710

PCR 1100 F/B/X/T HIRL CL

RWY 06: ALSF2. TDZL. REIL. PAPI(P4L)—GA 3.0° TCH 71'. RVR-TMR Trees.**RWY 24:** MALSR. TDZL. PAPI(P4L)—GA 3.0° TCH 71'. RVR-TMR Trees.**RWY 15-33:** H6847X150 (ASPH-GRVD) S-200, D-200, 2S-175, 2D-350 PCR 1100 F/B/X/T HIRL**RWY 15:** REIL. PAPI(P4L)—GA 3.5° TCH 61'. RVR-R Trees.**RWY 33:** MALSF. PAPI(P4R)—GA 3.0° TCH 72'. RVR-T Trees.**LAND AND HOLD—SHORT OPERATIONS**

LDG RWY	HOLD—SHORT POINT	AVBL LDG DIST
RWY 24	15-33	5850
RWY 33	06-24	4550

RUNWAY DECLARED DISTANCE INFORMATION**RWY 06:** TORA-9509 TODA-9509 ASDA-9509 LDA-9509**RWY 15:** TORA-6847 TODA-6847 ASDA-6847 LDA-6847**RWY 24:** TORA-9509 TODA-9509 ASDA-9509 LDA-9509**RWY 33:** TORA-6847 TODA-6847 ASDA-6847 LDA-6847

SERVICE: S4 **FUEL** 100LL, JET A **OX** 1, 2, 3, 4 **LGT** Unmonitored when afld clsd. Afld ops ltd to tenant acft when afld clsd. **MILITARY—JASU** (MD)-3 **FUEL** A++ (Mil) A, A+ (C860-627-3300.) (NC-100LL) **FLUID** SP LOX **OIL** O-128-133-148 (Mil) SOAP

AIRPORT REMARKS: Attended continuously. Numerous birds freq on or invof arpt. ANG: Opr 1200-2030Z‡ Mon, Tues, Fri; 1200-0400Z‡ Wed, Thu. 41.9 149.825 335.775 (Havoc Ops). NSTD wingtip clnc white dashed lines spanning bhnd front and back of acft prkg rows and white gnd eqpt boxes painted on ANG ramp. ANG- DSN 636-7519/7520.

C860-292-4519/4520. No trng flts, no practice apchs, no touch and go lds btn Mon-Sat 0400-1200Z‡ and Sun 0400-1700Z‡. BASH Phase II increased bird activity Sep-Oct and Mar-Apr. Rwy 6 de-ice pad clsd to acft with wingspan 171' or gtr exc with follow-me escort by arpt ops. Parl twy ops on Twy C and Twy B rstrd to acft with wingspans of 171' or less. Twy C btn Twy B and Twy C4 acft tax spd rstrn of 8 kts/10 mph max for acft with wingspan 214' or gtr.

TPA—1873(1700) heavy acft. Fixed wing acft use low idle for taxi, no engine checks or power runs allowed on the Rwy 06-24 245' by 200' blast pad SW end. Rwy 15-33 100' by 200' blast pad SE end. Lgtd obst ant 36' AGL/205' MSL (Rwy 24 ILS/GS Ant) 162' NW of Twy C cntrln marking btn Twy B and Twy C4. Non-based dvrsn acrs ctc arpt ops 860-627-3001 prior to divg & prvd co flt ops ctc info, acft type, POB, intl or dom flt & gnd ops agrmts. Only 1 intl acr jet bridge avbl for pax. ASDE-X in use. Operate transponders with altitude reporting mode and ADS-B (if equipped) enabled on all airport surfaces. Ldg fee for business, corporate and revenue producing acft. Flight Notification Service (ADCUS) avbl.

AIRPORT MANAGER: 860-292-2000**WEATHER DATA SOURCES:** ASOS 118.15 (860) 386-3480. WSP.**COMMUNICATIONS:** D-ATIS 118.15 (860-386-3570) UNICOM 122.95® **BRADLEY APP/DEP CON** 123.95 (061°-240°) 125.35 (241°-060°) 127.225**TOWER** 120.3 **GND CON** 121.9 **CLNC DEL** 121.75**CPDLC** (LOGON KUSA)**PDC****AIRSPACE:** CLASS C svc ctc **APP CON.****VOR TEST FACILITY (VOT)** 111.4**RADIO AIDS TO NAVIGATION:** NOTAM FILE HFD.**HARTFORD (L) (L) VORW/DME** 114.9 HFD Chan 96 N41°38.47' W72°32.85' 354° 18.9 NM to fld. 849/13W.**ILS/DME** 111.1 I-BDL Chan 48 Rwy 06. Class IIIE.**ILS/DME** 111.1 I-MYQ Chan 48 Rwy 24. Class IIE. DME unusable frm .4 NM inbd to Rwy 24.**ILS/DME** 108.55 I-IKX Chan 22(Y) Rwy 33. Class IE.