


MASON CO (T92) 3 SE UTC-6(-5DT) N30°43.93' W99°11.04'
 1514 B NOTAM FILE SJT
RWY 18-36: H3716X50 (ASPH) LIRL
RWY 18: PAPI(P2L)—GA 3.25° TCH 48'. Trees.
RWY 36: PAPI(P2L)—GA 3.0° TCH 44'.
SERVICE: FUEL 100LL
AIRPORT REMARKS: Unattended. Deer on and invof rwy. 100LL 24 hrs self serve. For assistance call 325-347-5252 (County Sheriff). Hvy tsnt tfc Nov-Jan.
AIRPORT MANAGER: 325-347-5556
COMMUNICATIONS: CTAF 122.9
 Ⓡ **HOUSTON CENTER APP/DEP CON** 132.35
CLEARANCE DELIVERY PHONE: For CD ctc Houston ARTCC at 281-230-5622.
RADIO AIDS TO NAVIGATION: NOTAM FILE AQO.
LLANO (L) TACAN Chan 19 LLO (108.2) N30°47.78' W98°47.24' 251° 20.9 NM to fld. 1207/8E.

SAN ANTONIO
 L-19C
 IAP



MAVERICK CO MEML INTL (See EAGLE PASS on page 318)

MAVERICK N32°52.15' W97°02.43' NOTAM FILE FTW.
(VH) (H) VORW/DME 113.1 TTT Chan 78 359° 1.7 NM to Dallas-Fort Worth Intl. 536/6E.
 All acft arriving DFW are requested to turn DME off until departure due to traffic overload of Maverick DME
 DME unusable:
 180°-190° byd 10 NM
 240°-260° byd 20 NM blo 3,500'
 VOR unusable:
 105°-110° byd 40 NM

DALLAS-FT. WORTH
 COPTER
 H-6H, L-17C, A