

PORT MANSFIELD**CHARLES R JOHNSON** (T05) 1 NW UTC-6(-5DT) N26°33.61' W97°26.36'BROWNSVILLE
L-20H, 21A

10 B NOTAM FILE SJT

RWY 12-30: H3200X50 (ASPH) S-21 MIRL**RWY 12:** P-line.**RWY 30:** P-line.**SERVICE:** LGT MIRL Rwy 12-30 preset low intst; to increase intst ACTVT—CTAF.**AIRPORT REMARKS:** Unattended. Harbor superintendent's ofc attended 1400-2250Z. Deer & birds on & invof arpt. Rwy 12 and Rwy 30 rwy mkgns discolored. Fee for ovnght tie down.**AIRPORT MANAGER:** 956-944-2325**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Corpus Christi Apch at 361-299-4230.**RADIO AIDS TO NAVIGATION:** NOTAM FILE HRL.**HARLINGEN (VL)(DH) VORW/DME** 113.65 HRL Chan 83(Y) N26°13.75' W97°39.14' 025° 22.9 NM to fd. 32/5E.**PORTLAND****HUNT** (9R5) 2 NW UTC-6(-5DT) N27°53.18' W97°20.97'

BROWNSVILLE

38 NOTAM FILE SJT

RWY 14L-32R: H2350X20 (ASPH) S-9 0.7% up NW**RWY 14L:** P-line. Rgt tfc.**RWY 32R:** Brush.**RWY 14R-32L:** 1400X60 (TURF-GRVL)**RWY 14R:** Rgt tfc.**NOISE:** Noise abatement procedures in effect. Call arpt manager at 361-643-3950.**AIRPORT REMARKS:** Unattended. Rwy 14R-32L CLOSED indef. Wind turbines N of arpt. Rwy 14L-32R has severe grass encroachment, pot holes, and loose gravel on rwy. Rwy 14R-32L heavy rutting along entire rwy length. Rwy 14L-32R limited line of sight between thld; southern 600' of rwy drops off approximately 8'. Rwy 32R ground drops off approximately 10' at thld.**AIRPORT MANAGER:** 361-643-3950**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Corpus Christi Apch at 361-299-4230.**POSSUM KINGDOM** (See GRAFORD on page 339)**POST-GARZA CO MUNI** (5F1) 2 E UTC-6(-5DT) N33°12.20' W101°20.29'

DALLAS-FT WORTH

L-6H

2545 B NOTAM FILE FTW

RWY 17-35: H4200X60 (ASPH) S-16 MIRL**RWY 17:** PAPI(P2L)—GA 3.0° TCH 20'.**RWY 35:** Road.**RWY 06-24:** H2210X60 (ASPH) S-16 MIRL 1.0% up SW**RWY 06:** Trees.**RWY 24:** Fence.**AIRPORT REMARKS:** Attended intmnt. Deer and feral hogs on and invof arpt. Rwy 06-24 and Rwy 17 pavement poor, seal coat spalling, loose stones and asphalt.**AIRPORT MANAGER:** 806-759-7561**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Fort Worth ARTCC at 817-858-7584.**RADIO AIDS TO NAVIGATION:** NOTAM FILE LBB.**LUBBOCK (L) VORTACW** 109.2 LBB Chan 29 N33°42.30' W101°54.84' 125° 41.7 NM to fd. 3310/11E.

VOR unusable:

040°-050° byd 38 NM blo 5,300'

210°-260° byd 25 NM blo 6,000'

PRESIDIO**BIG BEND RANCH STATE PARK** (3T9) 23 E UTC-6(-5DT) N29°28.27' W103°56.19'

EL PASO

H-7A, L-6J

4250 NOTAM FILE SJT

RWY 08-26: H5500X80 (ASPH/GRVL)**RWY 08:** Brush.**RWY 26:** Brush.**AIRPORT REMARKS:** Unattended. Arpt located 26 miles from ranch gate, road very rough. Upon arrival, check in at ranger station, 1 mile from arpt. Remote area, no cell phone coverage. Rwy 08-26 loose stones on rwy.**AIRPORT MANAGER:** 432-358-4444**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Albuquerque ARTCC at 505-856-4861.