

HI-TACAN Y RWY 32R

TACAN PAM Chan 64	APCH CRS 326°	Rwy Idg 10,008 TDZE 14 Arpt Elev 17
-----------------------------	-------------------------	--


[USAF]

TYNDALL AFB (KPAM)

ALSF-1
(A1)

MISSED APPROACH: Track outbound PAM TACAN R-320 to 3 DME (PIMLE), then turn right to join PAM R-104 to 20 DME (SUSIE) and hold. Maintain 3000.

ATIS ★ 254.4	APP CON 125.2 392.1 (N abv 5000') 120.825 379.3 (N blw 5000') 124.15 338.35 (S abv 5000') 119.775 317.45 (S blw 5000')	TOWER ★ 133.95 263.15	GND CON 121.9 259.3	ASR/PAR
------------------------	--	---------------------------------	-------------------------------	---------



3000 PAM R-320, **PIMLE PAM 3**, **SUSIE PAM 20**

VGSI and descent angles not coincident (VGSI Angle 2.50/TCH 50).

ELEV 17, **TDZE 14**

326°, **2.87° TCH 50**

32L, **32R**, **326°**

CATEGORY	C	D	E
S-32R *	480/50	466 (500-1)	
CIRCLING	540-1 1/2 523 (600-1 1/2)	580-2	563 (600-2)

Recommend Rwy 14L-32R for apch end engagement of A-Gear.

HIRL all rwys

HI-TACAN Y RWY 32R